


Attachments
previously
sent

17 7 0241

17473


de maximis, inc.

9041 Executive Park Drive
Suite 401
Knoxville, TN 37923
(615) 691-5052



November 16, 1992

Mr. Fred S. Stroud - OSC
USEPA - Region IV
345 Courtland Street, NE
Atlanta, GA 30365


**Reference: Saad Trousdale Drive Site
Transmittal of Analytical Data**

Dear Mr. Stroud:

Pursuant to Section VI Paragraph 8 of the Administrative Order by Consent (AOC) Docket No. 92-34-C, all analytical data collected at the site to date are transmitted with this letter. Attached with the data are the chain-of-custody/request for analyses forms, which were submitted to Specialized Assays with the samples, and the sample tracking forms. The sample tracking forms include a list of all samples collected from the Franklin Brick Trench (10-12-92 through 10-23-92), samples collected from the Klein Coach Trench (10-20-92 through 10-23-92), and samples collected from the Saad Site Trench (10-26-92 through 11-10-92). Samples denoted by an asterisk (*) on the sample tracking forms were submitted to the laboratory for analysis.

Please note that the sample results (attached) have not been subjected to full data validation procedures at this point. The quality control/quality assurance (QA/QC) validation process is not scheduled until the completion of site characterization/removal activities (see schedule in the RA/FI Phase II Work Plan). As such, these data should be considered as preliminary until DRE Remedial Services completes their QA/QC validation process in conformance with the project schedule and with the QA/QC requirements established in Section VI Paragraphs 7 and 8 of the AOC.

Respectively,
de maximis, inc.

A handwritten signature in cursive script, reading "Bennie L. Underwood".

Bennie L. Underwood
Project Coordinator

RLD/mdm

Attachments

cc: Beth Davis - ORC
Saad Site Technical Committee

File: data1/trcsk c: 3034